

ZyXEL NBG6716 Standard Version Release V1.00(AAKG.5)C0 Release Note

Date: Apr. 23, 2014

Supported Platforms:
NBG6716

Versions:
V1.00(AAKG.5)C0

Notes:

1. Default LAN IP: 192.168.1.1
2. Default password: 1234
3. Firmware upgrades may reset the router's configuration options to the factory defaults. Before performing an upgrade, please backup you current configuration first

Known Issues:

1. The default WPS PIN number of router is not available. Before use WPS PIN function, please enable WPS PIN code function first and then click Generate button to generate WPS PIN number
2. After plug-in/out USB device, the FTP server could not be accessed temporarily around 10 seconds
3. The maximum number of simultaneous connections for FTP server is 10
4. Please force to set UTF-8 in FTP client software to avoid characters problems
5. For Windows XP user to access SAMBA folder, please use "Map Network Drive" method to access with login username and password
6. The user account and password of SAMBA and FTP server didn't support #, &, + characters
7. For StreamBoost related web pages display compatibility, please use browsers: IE (9-10), Firefox (21+), Safari, (6+), Chrome (26+)
8. The StreamBoost Network page can't display properly with the latest Google Chrome (34.0.1847.116) version.

Modification in V1.00(AAKG.5)C0 | 04/23/2014

1. [Feature Enhancement]
Add IPv6 dual stack and 6rd features
2. [Feature Enhancement]
Add Parental control features
3. [Feature Enhancement]
StreamBoost performance enhancement

4. **[Bug Fixed]**
In AP mode, the DNS Server IP lost after reboot
5. **[Bug Fixed]**
5GHz channel can't display properly in GUI
6. **[Bug Fixed]**
USB Disk file system FAT, FAT32, NTFS, EXT3, EXT3 compatibility enhancement
7. **[Bug Fixed]**
In AP mode, can't access from Internet to a LAN connected device behind the NBG6716
8. **[Bug Fixed]**
DUT can't work properly after plug in USB disk with logical partition
9. **[Bug Fixed]**
5GHz channel can't be selected properly

Modification in V1.00(AAKG.4)C0 | 11/25/2013

1. **[Bug Fixed]**
Fixed the issue that Port Forwarding GUI can't display properly in French language

Modification in V1.00(AAKG.3)C0 | 11/13/2013

1. **[Bug Fixed]**
Fixed the issue that incorrect time after restarting router with static IP WAN type
2. **[Bug Fixed]**
Fixed wireless channel number incorrect display issue
3. **[Bug Fixed]**
Fixed StreamBoost related page can't display issue
4. **[Feature Changed]**
The Eazy123 wireless setting apply to both 2.4GHz and 5GHz wireless interface

Modification in V1.00(AAKG.2)C0 | 08/12/2013

1. **[Feature Changed]**
USB access via SAMBA without authentication if none User Account enabled
2. **[Feature Changed]**
Configuration menu expanded by default
3. **[Feature Changed]**
Added feature that limit cache memory usage when access files on USB storage via SAMBA, FTP, DLNA protocol
4. **[Bug Fixed]**
Fixed error message on Packet Statistics GUI when disabled Wi-Fi
5. **[Bug Fixed]**
Modified the sentence for Deutsch on Sys OP Mode while system restarting
6. **[Bug Fixed]**
Fixed the 2.4GHz low throughput issue with NWD6505

Modification in V1.00(AAKG.1)C0 | 07/23/2013

1. [Feature Changed]

Modify the StreamBoost Update server address

Modification in V1.00(AAKG.0)C0 | 07/08/2013

1. The first time firmware release