HP ProCurve RF Manager 5.9 and MSM415 Sensor (802.11n) Technical NPI Training
Erratum

Some of the web based training slides have been updated after the recording took place.

The following change have been made;

In Slide 33, all references to Cisco integration within RF Manager 5.9 under the bullet 'The WLSE-managed Cisco LWAPP AP1010' have been removed.