

P280/Eleven Hundred | Troubleshooting KUHLER H₂O Liquid Cooler Installation Addendum

When installing your KUHLER H₂O liquid cooling system in your P280/Eleven Hundred, there is a chance that the fan power hub is installed in such a way that the radiator will not fit correctly.

In order to correct this:

1. Uninstall the 3-pin power connectors from the fan power hub located in the rear of the case.
2. Unscrew the four screws holding the power hub in place.
3. Rotate the power hub such that the Molex connector is at the top and the 3-pin power connectors are at the bottom.
4. Use the screws to secure the power hub back into place.
5. Attach/reattach 3-pin fans to the power hub.

Your KUHLER H₂O radiator will now have sufficient space to be installed. Install the device as documented in the installation guide that came with the product.



Loosen the power hub by removing the four screws.



Reinstall the power hub in the correct orientation.



The radiator will then have sufficient clearance.