

# Release Notes for Cisco RV320/RV325 Routers Firmware Version 1.1.1.06

## April 2014

This document describes resolved issues and known issues in Cisco RV320/RV325 Firmware Version 1.1.1.06.

**NOTE** We recommend that you reset your device to use default settings when you upgrade to version 1.1.1.06 and reconfigure your settings to include these new features.

## Contents

[Resolved Issues, page 1](#)

[Known Issues, page 3](#)

[Related Information, page 5](#)

## Resolved Issues

- RV320: Users could enter ampersand (&) and percentage (%) symbols in the PPPOE username field. (CSCue64461)
- IP/MAC binding clients of a non-default VLAN are unable to access the Internet. (CSCug28848)
- When the host name or the domain name is modified, the web GUI displays an error. (CSCue24358)
- Users are unable to modify or save custom services. (CSCui03038)

## Release Notes

---

- Client devices behind 6rd tunnels are unable to ping each other. (CSCui03071)
- When users update the Priority field in the Protocol Binding Table, the priority is set incorrectly. (CSCuh97775)
- For some NICs, such as Intel 82579LM, when Energy-Efficient Ethernet (EEE) is enabled for a LAN port, data traffic does not pass through the data link and the Link Status is incorrectly displayed as connected. (CSCuh83162)
- When users disconnect a USB dongle, the GUI continues to display the status as connected. (CSCuh59490)
- DHCP relay fails over LAN and through VPN tunnel if the server is not in the default VLAN (CSCuh91354)
- An error is encountered when more than 26 port forwarding entries are added. (CSCuj43055)
- When the device is kept running for many days continuously, the device faces a memory leak and crashes. (CSCuj36179)
- The firewall SynFlood and DoS attack threshold was high and prevented traffic from VPN peers. (CSCuj57476)

---

## Known Issues

### Caveats Acknowledged in Release 1.1.1.06

#### Virtual Passage Adapter Fails on Win7 (64bit) with IE10, and Win8.1 with IE11

:SSL VPN virtual passage adapter does not work on Windows 7 (64 bit) with IE10, and on Windows 8.1 with IE11.

**Solution:** None.

#### System Summary Page Does not Display LAN IPv6 Address

The System Summary page does not display the LAN interface IPv6 address. (CSCu170357)

**Solution:** None

#### Cannot Establish VPN Tunnel when Security Group is Changed

When the local security group changed, the VPN tunnel cannot be established. (CSCu155278)

**Solution:** Save the VPN policy again after changing the LAN address.

#### Cannot Change Hostname if LAN IP is in the 192.168.x.100-150 range

Unable to change the hostname or the domain name if the LAN IP is in the range of 192.168.x.100-150. (CSCu16754)

**Solution:** Change the hostname or the domain name to the default LAN address 192.168.1.1, then change the LAN IP address to 192.168.x.x.

### Issue Carried over from Release 1.1.0.09

#### IPsec VPN Clients Cannot Connect to EZVPN by using Split Mode (CSCu125163)

iPhones, iPads, and iPods have difficulty establishing a VPN tunnel for EZVPN split mode.

**Solution:** Use EZVPN full tunnel mode.

### **VPN Cannot Access HTTP/HTTPS when Device behind NAT (CSCuf24407)**

SSL VPN clients are unable to access the HTTP/HTTPS service when the device is behind NAT.

**Solution:** None.

### **RDP Cannot be Established through SSL VPN on Win 8 32-bit and Win8 64-bit (CSCui00878)**

Remote Desktop Protocol (RDP) does not work through an SSL VPN tunnel on Windows 8.

**Solution:** None.

## Related Information

Support	
Cisco Small Business Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Small Business Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Cisco Small Business Firmware Downloads	<a href="http://www.cisco.com/go/software">www.cisco.com/go/software</a> Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco Small Business RV Series Routers	<a href="http://www.cisco.com/go/smallbizrouters">www.cisco.com/go/smallbizrouters</a>
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Cisco Small Business Home	<a href="http://www.cisco.com/smb">www.cisco.com/smb</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.

78-21191-03