



DIR-813 Firmware Release Notes

Firmware: FW2.08.B02

Hardware: B1

Date: 2015/11/09

Note:

None

Problems Resolved:

1. Fixed error message on PPPoE mode in Easy Setup page.
2. Fixed daylight saving time issue reported by Brazil region.
3. Fixed the router crash issue found after user clicks the Wireless Status page in AP or Repeater mode.
4. Fixed the issue found with user can't set URL with capitals in URL filter function
5. Revised the MAC address format (upper case) in hidden page.
6. Fixed the issue found when a user uploads a firmware file in an incorrect format to the router, it may cause the system to reboot.
7. Fixed the issue when a user turns OFF the 2.4GHz wireless radio, but leaves the 5GHz wireless radio ON, the router won't allow wireless clients connection using the WPS PIN method.

Enhancements:

1. Improved stability of PPPoE dial-up feature.
2. Improved wireless connection stability with iOS.

Known Issues:

None

Firmware: FW2.07.B03 (Released)

Hardware: B1

Date: 2015/09/08

Note:

First release

Problems Resolved:

None

Enhancements:

None

Known Issues:

None