

Product End-of-Life Disassembly Instructions

Product Category: Monitors and Displays

Marketing Name / Model [List multiple models if applicable.]

HP ProDisplay P191 18.5-inch LED Backlit Monitor

Purpose: The document is intended for use by end-of-life recyclers or treatment facilities. It provides the basic instructions for the disassembly of HP products to remove components and materials requiring selective treatment, as defined by EU directive 2002/96/EC, Waste Electrical and Electronic Equipment (WEEE).

1.0 Items Requiring Selective Treatment

- 1.1 Items listed below are classified as requiring selective treatment.
- 1.2 Enter the quantity of items contained within the product which require selective treatment in the right column, as applicable.

Item Description	Notes	Quantity of items included in product
Printed Circuit Boards (PCB) or Printed Circuit Assemblies (PCA)	With a surface greater than 10 sq cm	3
Batteries	All types including standard alkaline and lithium coin or button style batteries	0
Mercury-containing components	For example, mercury in lamps, display backlights, scanner lamps, switches, batteries	0
Liquid Crystal Displays (LCD) with a surface greater than 100 sq cm	Includes background illuminated displays with gas discharge lamps	1
Cathode Ray Tubes (CRT)		0
Capacitors / condensers (Containing PCB/PCT)		24
Electrolytic Capacitors / Condensers measuring greater than 2.5 cm in diameter or height		0
External electrical cables and cords		2
Gas Discharge Lamps		0
Plastics containing Brominated Flame Retardants weighing > 25 grams (not including PCBs or PCAs already listed as a separate item above)		0
Components and parts containing toner and ink, including liquids, semi-liquids (gel/paste) and toner	Include the cartridges, print heads, tubes, vent chambers, and service stations.	0
Components and waste containing asbestos		0
Components, parts and materials containing refractory ceramic fibers		0

EL-MF877-00 Template Revision B

Components, parts and materials containing	0
radioactive substances	

2.0 Tools Required

List the type and size of the tools that would typically be used to disassemble the product to a point where components and materials requiring selective treatment can be removed.

Tool Description	Tool Size (if applicable)
Description #1 SCREW DRIVER	#2
Description #2	
Description #3	
Description #4	
Description #5	
2.0 Product Disassembly Process	

3.0 Product Disassembly Process

- 3.1 List the basic steps that should typically be followed to remove components and materials requiring selective treatment:
- 1. Dismantle the screws of stand, get down the stand
- 2. Dismantle the Rear cover of monitor
- 3. Dismantle the of Bezel of monitor
- 4. Dismantle the screws from Mainframe
- 5. Pull out the PIN of FFC cable, separate the mainframe and Panel
- 6. Dismantle the PCBA screws
- 7. Take off board
- 8.

3.2 Optional Graphic. If the disassembly process is complex, insert a graphic illustration below to identify the items contained in the product that require selective treatment (with descriptions and arrows identifying locations).

Disassembly Flowchart for HP P191 Model

Issue Date:2012.10.22 Initiator: caihong long

Tool	Photo
#1 Crossing Screw Driver	
#1 Crossing Screw Driver	
N/A	
#1 Crossing Screw Driver	
N/A	
N/A	
N/A	
	#1 Crossing Screw Driver #1 Crossing Screw Driver N/A #1 Crossing Screw Driver

1		
Remove the FFC connector from Panel.	N/A	
Chassis assembly and panel	N/A	
Remove the Mylar from chassis	N/A	
Remove the FFC wire from PCBA	N/A	
Unlock the 2screws which fix the IF board to the chassis,	#2 Crossing Screw Driver	
Unlock the 6screws which fix the IF & Power PCBA	#1 Crossing Screw Driver	