

ESR9855G Changelog

Release Date Sep 1, 2010

Firmware :1.0.08	HW Version :
------------------	--------------

- **Changed**
- Add MSSID on V1.0.08

Release Date April 1, 2010

Firmware :1.0.07	HW Version :
------------------	--------------

- **Changed**
- Modify some "add" button GUI issue

Release Date April 1, 2010

Firmware :1.0.06	HW Version :
------------------	--------------

- **Changed**
- Modify region domain code FCC = 0x3a

Release Date March 25, 2010

Firmware :1.0.05	HW Version :
------------------	--------------

- **Changed**
- Modify wireless restart issue

Release Date Jan 26, 2010

Firmware :1.0.04	HW Version :
------------------	--------------

- **Changed**
- modify 11G low throughput issue
- modify GUI wizard wireless display ssid issue

Release Date Jan 21, 2010

Firmware :1.0.03	HW Version :
------------------	--------------

- **Changed**
- modify SSID alert issue
- modify GUI Wi-Fi Protected Setup issue
- modify Virtual server,Special Applications,Port Forwarding,Router GUI design follow PM/SQA request
- modify Save configure setting issue
- modify reload fail settings issue
- modify inbound filter GUI issue
- modify FCC/ETSI issue

Release Date Jan 12, 2010

Firmware :1.0.02	HW Version :
------------------	--------------

- **Changed**
- Modify GUI issue follow PM request(ex: picture,remover wan wizard ..etc)

Release Date Jan 08, 2010

Firmware :1.0.01	HW Version :
------------------	--------------

- **Changed**
- WLAN Driver Change to Atheros
- Base on wl-350 firmware
- add windows 7 pre-test function
- modify SQA issue for web GUI (ex: SQA issue 2.6.1.2.1 , 2.5.6.4, 2.24.1, 2.26.24, 2.33, 7.2.4, 2.4.1, 2.5.2.10, 2.5.3.5, 2.5.4.6)
-